

Release Notes

Version	Comment	Supported Grippers	Interface
1.0.3 Compatibility: YRC 1000 micro with controller software version <= YBS 3.05 Pendant Software: 2.2	Changelog: Added support for new gripper firmware v. 5.2 features: - Brake Test - “Not feasible reason” is displayed in the plugin status bar - Jogging with velocity MotoPlus Application: Fixed Bug that some commands are not executed when sending commands in a short time to the gripper. Parameter grip prehold time was not read correctly from the gripper Utility: Corrected limits for gripping velocity Required Options: EtherNet/IP – Scanner Option available Known issues: -	EGU: all types with firmware version 5.1 and 5.2 EGK: all types with firmware version 5.1 and 5.2	EtherNet/IP
1.0.1 Compatibility: YRC 1000 micro with controller software version <= YBS 2.49 Pendant Software: 2.2	Changelog: Initial Version Required Options: EtherNet/IP – Scanner Option available Known issues: -	EGU: all types with firmware version 5.1 EGK: all types with firmware version 5.1	EtherNet/IP