

Release Notes

Version	Comment	Supported Grippers	Interface
1.0.4 Compatibility: YRC 1000 micro with controller software version = YBS 4.16 Pendant Software: 4.0.2	Changelog: Added support for EZU Gripper series Firmware V5.3 support Required Options: EtherNet/IP – Scanner Option available Known issues: Gripper name can not be changed Controller Version must be ≥ 4.16 Pendant Version must be $\geq 4.0.2$	EGU: all types with firmware version 5.1, 5.2, 5.3 EGK: all types with firmware version 5.1, 5.2, 5.3 EZU: all types with firmware version 5.3	EtherNet/IP
1.0.3 Compatibility: YRC 1000 micro with controller software version $\leq$ YBS 3.05 Pendant Software: 2.2	Changelog: Added support for new gripper firmware v. 5.2 features: - Brake Test - “Not feasible reason” is displayed in the plugin status bar - Jogging with velocity MotoPlus Application: Fixed Bug that some commands are not executed when sending commands in a short time to the gripper. Parameter grip prehold time was not read correctly from the gripper Utility: Corrected limits for gripping velocity Required Options: EtherNet/IP – Scanner Option available Known issues: -	EGU: all types with firmware version 5.1 and 5.2 EGK: all types with firmware version 5.1 and 5.2	EtherNet/IP
1.0.1	Changelog: Initial Version	EGU: all types with firmware version 5.1	EtherNet/IP

Compatibility: YRC 1000 micro with controller software version <= YBS 2.49 Pendant Software: 2.2	Required Options: EtherNet/IP – Scanner Option available Known issues: -	EGK: all types with firmware version 5.1	
--	--	---	--