

# Release Notes EGK EGU

## Siemens FB IO-Link Acyclic

| Version                                                     | Comment                                                                                                                                                                                                                                                                                                                                                           | Supported Device | Interface   |
|-------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------|
| <b>1.0.4</b><br><br><b>Compatibility:</b><br>Siemens TIA 17 | <b>Changelog:</b><br>Input variable "i_Port" implemented to directly specify the port of the master.<br>This made it compatible with Siemens IO-Link masters of<br>the ET200ECO,<br>the ET200SP,<br>the CM module of the 1500 series<br>and<br>the SM module of the 1200 series<br>Text Fixes<br><b>Required Options:</b><br>none<br><b>Known issues:</b><br>none | EGU<br>EGK       | IO-Link 1.1 |
| <b>1.0.3</b><br><br><b>Compatibility:</b><br>Siemens TIA 17 | <b>Changelog:</b><br>removed the Master selection. The CAP number must now be entered directly as some master manufacturers have new numbers.<br><b>Required Options:</b><br>none<br><b>Known issues:</b><br>none                                                                                                                                                 | EGU<br>EGK       | IO-Link 1.1 |
| <b>1.0.2</b><br><br><b>Compatibility:</b><br>Siemens TIA 17 | <b>Changelog:</b><br><b>Changed IOLink_Device Funktion Block from V4.0 to V5.0</b><br><b>Required Options:</b><br>none<br><b>Known issues:</b>                                                                                                                                                                                                                    | EGU<br>EGK       | IO-Link 1.1 |

|                                                             |                                                                                                                     |            |             |
|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|------------|-------------|
|                                                             | none                                                                                                                |            |             |
| <b>1.0.1</b><br><br><b>Compatibility:</b><br>Siemens TIA 17 | <b>Changelog:</b><br>Bug fixing at Read Prozess<br><b>Required Options:</b><br>none<br><b>Known issues:</b><br>none | EGU<br>EGK | IO-Link 1.1 |
| <b>1.0.0</b><br><br><b>Compatibility:</b><br>Siemens TIA 17 | <b>Changelog:</b><br>Release Funktion Block<br><b>Required Options:</b><br>none<br><b>Known issues:</b><br>none     | EGU<br>EGK | IO-Link 1.1 |